

Department of Defense Standardization Program



ASSIST UPDATE

(A bi-monthly summary of changes to the ASSIST document database)

1 November 2011

(For the Period 15 October 2011 to 31 October 2011)

ASSIST UPDATE

Documents listed in the ASSIST UPDATE have an indicator of “N” or “M” to describe the last action taken on a listed document.

“N” indicates that a “new” document has been entered into the ASSIST database.

“M” indicates that a document already in ASSIST has been “modified” in some way.

The ASSIST UPDATE is published twice a month and provides a summary of changes to Department of Defense standardization documents for the period indicated. Since changes are processed to the ASSIST database on a daily basis, users should consult the ASSIST web site at <https://assist.daps.dla.mil> for the most current information.

If you need to track changes more frequently, or if you have an interest in specific Federal Supply Classes or individual specifications, standards, or other standardization documents, you may wish to take advantage of the ASSIST Alert Service. This feature lets you establish a list of documents of interest to you, and then the ASSIST will alert you with an E-mail message each day there is a change to one or more documents of interest to you. There is no charge for this service; however, you must have an ASSIST user account. To obtain one, complete the ASSIST online registration form at <https://assist.daps.dla.mil/online/registration/registration.cfm>.

Once you have your account, you can establish your Alert Portal profile. For more information on the ASSIST Alert Service, go to: <https://assist.daps.dla.mil/online/news/AlertService.htm>.

ACTIVE SECTION

ASSIST UPDATE

| LAST ACTION | DOCUMENT NUMBER | DOCUMENT TITLE | DISTRIBUTION | FSC/AREA | MCA | PREP ACTY | DATE |
|-------------|------------------------|---|--------------|----------|-----|-----------|-------------|
| M | MIL-DTL-1311F(1) | Cartridge, Caliber .45, Ball - M1911 [CUST: AR OS 99] [REVIEW: 40 70 AS MC MR NP] | D | 1305 | | AR | 22-MAR-2011 |
| M | MIL-DTL-3498C(1) | Cartridges, Dummy (for Small Arms) [CUST: AR OS 99] [REVIEW: 40 70 AS MC MR NP] | D | 1305 | | AR | 11-SEP-2011 |
| M | MIL-DTL-46550D | Charge, Demolition, Shaped, 40lb. M3A1, Metal Parts Assembly [CUST: AR] | A | 1375 | | AR | 11-SEP-2011 |
| M | MIL-DTL-46594C | Charge, Demolition, Shaped, 40 LB. M3A1 Loading, Assembling and Packing [CUST: AR] | A | 1375 | | AR | 11-SEP-2011 |
| N | MIL-PRF-32390 | Engaging Device, Aircraft Arresting System - USAF Pendant Cable Retraction Systems (PCRS) [CUST: 84] [REVIEW: 99] | A | 1710 | | 84 | 27-OCT-2011 |
| N | MIL-DTL-32392 | Aircraft Arresting System - Textile (TAAS) [CUST: 84] [REVIEW: 99] | A | 1710 | | 84 | 27-OCT-2011 |
| M | MIL-DTL-27516G | Hose and Hose Assembly, Nonmetallic, Suction and Discharge [CUST: AT AS 99 CC] [REVIEW: 70 71 AV MC SA] | A | 4720 | | CC | 19-OCT-2011 |
| N | EI-1529 | Aviation Fuelling Hose and Hose Assemblies [CUST: CR4 YD 99 CC] [REVIEW: 71 AS SH] | A | 4720 | | CC | 05-OCT-2011 |
| M | MS9769B(1) | Reducer, Tube - Straight, Tube to Boss [CUST: AS 99 CC] [REVIEW: 71 MC SA] | A | 4730 | | CC | 12-OCT-2011 |
| M | MIL-DTL-24694A | Valve, Hydraulic Relief, 1.5 - 35 Bars (22 - 500 Pounds Per Square Inch) Cartridge Type, General Specification (Metric) [CUST: SH] | A | 4810 | | SH | 04-OCT-2011 |
| M | MIL-DTL-24704B | Flanges, Four Bolt Square, Hydraulic General Specification for [CUST: SH] | A | 4810 | | SH | 04-OCT-2011 |
| M | A-A-50310A | Spray Gun, Paint, Heavy Duty (Siphon or Pressure Feed) [CUST: AR MC 99 CC] | A | 4940 | / | CC | 19-OCT-2011 |
| M | A-A-55543C | Gun, Air Blow, (Blast Cleaning) [CUST: AR AS 99 CC] [REVIEW: 84] | A | 4940 | / | CC | 19-OCT-2011 |
| M | MS3211B | Ring, Retainer, External [CUST: MI OS IS] | A | 5325 | | IS | 25-OCT-2011 |
| M | MS3215C | Ring, Retaining, External, "E", Reinforced (Reduced Section Type) [CUST: AR OS 99 IS] [REVIEW: MI] | A | 5325 | | IS | 25-OCT-2011 |
| M | MS3216D | Ring, Retaining, External, Prong-Lock (Reduced Section Type) [CUST: AR OS 99 IS] [REVIEW: AT CR4 MC MI] | A | 5325 | | IS | 25-OCT-2011 |
| M | MS3217C | Ring, Retaining, External, Heavy-Duty (Tapered Section Type) [CUST: AR OS 99 IS] | A | 5325 | | IS | 25-OCT-2011 |
| M | MIL-PRF-39014/22F | Capacitors, Fixed, Ceramic Dielectric (General Purpose), Established Reliability, Styles CKR22, CKR23, and CKR24 [CUST: CR EC 85 CC NA] [REVIEW: 19 99 AR AT AV CR4 MC MI] | A | 5910 | | CR | 28-OCT-2011 |
| M | MIL-PRF-39022/1G | Capacitors, Fixed, Metallized, Paper-Plastic Film, or Plastic Film Dielectric, Direct Current, (Hermetically Sealed in Metal Cases), Established Reliability, Style CHR09 (Insulated) [CUST: CR EC 85 CC] [REVIEW: 19 99 AR AS CG MC OS SH] | A | 5910 | | CC | 24-OCT-2011 |
| M | MIL-PRF-39022/2G | Capacitors, Fixed, Metallized, Paper-Plastic Film, Dielectric, Direct Current, (Hermetically Sealed in Metal Cases), Established Reliability, Style CHR19 (Insulated) [CUST: CR EC 85 CC] [REVIEW: 19 99 AR AS CG MC OS SH] | A | 5910 | | CC | 24-OCT-2011 |
| M | MIL-PRF-55681/1F NOT 1 | Capacitors, Chip, Multiple Layer, Fixed, Ceramic Dielectric, Established Reliability and Non-Established Reliability, Styles CDR01, CDR02, CDR03, and CDR04 [CUST: CR EC 85 CC] [REVIEW: 19 99 AS MC MI OS SH] | A | 5910 | | CR | 20-OCT-2011 |
| M | MIL-PRF-55681/2D NOT 1 | Capacitors, Chip, Multiple Layer, Fixed, Ceramic Dielectric, Established Reliability and Non-Established Reliability, Style CDR05 [CUST: CR EC 85 CC] [REVIEW: 19 99 AS MC OS SH] | A | 5910 | | CR | 20-OCT-2011 |
| M | MIL-PRF-55681/3E NOT 1 | Capacitors, Chip, Multiple Layer, Fixed, Ceramic Dielectric, Established Reliability and Non-Established Reliability, Style CDR06 [CUST: CR EC 85 CC] [REVIEW: 19 99 AS MC OS SH] | A | 5910 | | CR | 20-OCT-2011 |
| M | MIL-PRF-55681/5E NOT 1 | Capacitors, Chip, Multiple Layer, Fixed, Ceramic Dielectric, Established Reliability and Non-Established Reliability, Styles CDR21, CDR22, CDR23, CDR24, and CDR25 (High Frequency) [CUST: CR EC 85 CC] [REVIEW: 19 99 AS MC OS SH] | A | 5910 | | CR | 20-OCT-2011 |
| M | MIL-PRF-55681/7C NOT 1 | Capacitors, Chip, Multiple Layer, Fixed, Ceramic Dielectric, Established Reliability and Non-Established Reliability, Style CDR31, Metrix [CUST: CR EC 85 CC] [REVIEW: 19 99 AS MC OS SH] | A | 5910 | | CR | 20-OCT-2011 |
| M | MIL-PRF-55681/8C NOT 1 | Capacitors, Chip, Multiple Layer, Fixed, Ceramic Dielectric, Established Reliability and Non-Established Reliability, Style CDR32, Metric [CUST: CR EC 85 CC] [REVIEW: 19 99 AS MC OS SH] | A | 5910 | | CR | 20-OCT-2011 |
| M | A-A-55569C | Fuse, Inclosed Link, Automotive Blade Type, General Requirements for [CUST: EC CC] | A | 5920 | / | CC | 12-OCT-2011 |
| M | A-A-55569/1C | Fuse, Inclosed Link, Fast Acting, 1 Ampere (A) Through 40 A, Automotive Blade Type [CUST: EC CC] | A | 5920 | / | CC | 12-OCT-2011 |
| M | A-A-55569/2D | Fuse, Inclosed Link, Fast Acting, 2 Amperes (A) through 30 A, Miniature, Automotive Blade Type [CUST: EC CC] | A | 5920 | / | CC | 12-OCT-2011 |
| M | A-A-55569/3C | Fuse, Inclosed Link, Slow Blowing, 20 Amperes (A) through 80 A, Automotive Blade Type [CUST: EC CC] | A | 5920 | / | CC | 12-OCT-2011 |
| M | MIL-PRF-83383E(2) | Circuit Breakers, Remote Control, Thermal, Trip Free General Specification For [CUST: CR AS 85 CC] [REVIEW: 99 AT AV CR4 MI] | A | 5925 | | CC | 25-OCT-2011 |
| M | MIL-PRF-83383/4F | Circuit Breakers, Remote Control, AC-DC, Thermal, Trip-Free, Series Trip, Triple Pole, Auxiliary Contacts (5 to 100 Amperes) [CUST: CR AS 85 CC] | A | 5925 | | CC | 25-OCT-2011 |
| M | A-A-59886/1A | Circuit Breakers, Miniature, Thermal Magnetic, Shock Enhanced, Trip-Free, Series Trip, High Density Design, 35 MM Din Channel Mount, One Pole, 0.2 to 30 Amperes (A) [CUST: EC CC] | A | 5925 | / | CC | 27-OCT-2011 |
| M | A-A-59886/2A | Circuit Breakers, Miniature, Thermal Magnetic, Shock Enhanced, Trip-Free, Series Trip, High Density Design, 35 MM Din Channel Mount, Two Pole, 0.2 TO 30 Amperes (A) [CUST: EC CC] | A | 5925 | / | CC | 27-OCT-2011 |
| M | A-A-59886/3A | Circuit Breakers, Miniature, Thermal Magnetic, Shock Enhanced, Trip-Free, Series Trip, High Density Design, 35 MM Din Channel Mount, Three Pole, 0.2 to 30 Amperes (A) [CUST: EC CC] | A | 5925 | / | CC | 27-OCT-2011 |
| M | MS24612L | Switch, Toggle, Positive Break, Lever Lock, Environmentally Sealed, Screw Terminal, Single Pole, .469 Mounting Bushing, 25 Amperes [CUST: CR AS 85 CC] [REVIEW: 99 AR EC MI] | A | 5930 | | CC | 05-OCT-2011 |
| M | MS24613K | Switch, Toggle, Positive Break, Lever Lock, Environmentally Sealed, Screw Terminal, Double Pole, .469 Mounting Bushing, 25 Amperes [CUST: CR AS 85 CC] [REVIEW: 99 AR EC MI] | A | 5930 | | CC | 05-OCT-2011 |
| M | MS25306K | Switch, Toggle, Positive Break, Environmentally Sealed, Screw Terminal, Single Pole, .469 Mounting Bushing, 25 Amperes [CUST: CR AS 85 CC] [REVIEW: 99 AR AV EC MI] | A | 5930 | | CC | 05-OCT-2011 |
| M | MS25307L | Switch, Toggle, Positive Break, Lever Lock, Environmentally Sealed, Screw Terminal, Double Pole, .469 Mounting Bushing, 25 Amperes [CUST: CR AS 85 CC] [REVIEW: 99 AR AV EC MI] | A | 5930 | | CC | 05-OCT-2011 |
| M | MS25308L | Switch, Toggle, Positive Break, Lever Lock, Environmentally Sealed, Screw Terminal, Four Pole, .469 Mounting Bushing, 25 Amperes [CUST: CR AS 85 CC] [REVIEW: 99 AR EC MI] | A | 5930 | | CC | 05-OCT-2011 |
| M | MIL-DTL-24558B SUP 1 | Terminal Boxes, Connection, for Electrical and Electronic Systems, General Specification for [CUST: SH GS] | A | 5940 | | GS4 | 03-OCT-2011 |
| M | MIL-DTL-24558/20B | Terminal Box, Connection, Submersible (15-Foot), 10-Terminal, 20-Wire, 1000 Volts, Symbol No. 529 [CUST: SH GS] | A | 5940 | | GS4 | 03-OCT-2011 |
| M | MIL-DTL-24558/21B | Terminal Box, Connection, Submersible (15-Foot), 500 Volts, Symbol No. 476.1, 24 Lugs for Twelve 2-Conductor 23 MCM Cables or Eight 3-Conductor 23 MCM Cables [CUST: SH GS] | A | 5940 | | GS4 | 03-OCT-2011 |

ASSIST UPDATE

01-NOV-2011

ACTIVE SECTION

ASSIST UPDATE

| LAST ACTION | | | DISTRIBUTION | FSC/AREA | MCA | PREP ACTY | DATE |
|-------------|--------------------|--|--------------|----------|-----|-----------|-------------|
| | DOCUMENT NUMBER | DOCUMENT TITLE | | | | | |
| M | A-A-59499B | Battery, Dry, BA-59 [CUST: CR SH CC] [REVIEW: AV MC MI] | A | 6135 | / | CC | 15-OCT-2011 |
| M | MIL-DTL-7788H | Panels, Information, Integrally Illuminated [CUST: AV AS 99 GS] [REVIEW: IS] | A | 6220 | | GS2 | 18-OCT-2011 |
| M | MIL-DTL-51490C(2) | Detector Kit, Chemical Agent: M256A2 [CUST: EA SH 99] | X | 6665 | | EA | 17-OCT-2011 |
| M | MIL-DTL-7601C | Gage, Emergency Oxygen, Type L-2 [CUST: AS 99 GS] [REVIEW: 71] | A | 6685 | | GS1 | 17-OCT-2011 |
| M | A-A-58044A | N-Methylpyrrolidone [CUST: 68 GS] | A | 6810 | / | 68 | 27-OCT-2011 |
| M | MIL-PRF-11090J | Cleaning Compound, Degreasing and Depreserving Solvent [CUST: MR OS GS] [REVIEW: EA] | A | 6850 | | GS3 | 18-OCT-2011 |
| M | QPL-87937-13 NOT 1 | Cleaning Compound, Aerospace Equipment (Replaced by the Qualified Products Database (QPD) See Notice 1 for Additional Information) | A | 6850 | | 68 | 27-OCT-2011 |
| M | MIL-DTL-83133H | Turbine Fuel, Aviation, Kerosene Type, JP-8 (NATO F-34), NATO F-35, and JP-8+100 (NATO F-37) [CUST: AT AS 68 PS] [REVIEW: 11 AR AV] | A | 9130 | | 68 | 25-OCT-2011 |
| M | MIL-PRF-25508H | Propellant, Oxygen [CUST: MI AS 68 PS] [REVIEW: 19 LS NA] | A | 9135 | | 68 | 27-OCT-2011 |
| M | MIL-STD-881C | Work Breakdown Structures for Defense Materiel Items [CUST: MI SH 10] [REVIEW: 11 16 19 70 71 84 AR AS AT AV CR MC OS] [AMSC: D9213] | A | MISC | | WB | 03-OCT-2011 |
| M | MIL-STD-3018(1) | Parts Management [CUST: MI AS 85 DH] [REVIEW: 11 13 19 70 71 84 99 AR AT CC CH CR EA EC GS IS MC OS SH] [AMSC: D7730] | A | STDZ | | SO | 27-OCT-2011 |
| M | MIL-STD-188-110C | Interoperability and Performance Standards for Data Modems [CUST: CR EC 71] [REVIEW: 02 07 DC1 MC NS] | A | TCSS | | 71 | 23-SEP-2011 |
| M | MIL-DTL-5288J | Manuals, Technical and Checklists - Preparation of Cargo Aircraft Loading and Off-Loading [CUST: TM AS 16] [REVIEW: 11 99 AV MT] | A | TMSS | | 16 | 06-OCT-2011 |

INACTIVE SECTION

ASSIST UPDATE

| LAST ACTION | DOCUMENT NUMBER | DOCUMENT TITLE | DISTRIBUTION FSC/AREA | MCA PREP ACTY | DATE |
|-------------|-----------------------|--|--------------------------|------------------|-------------|
| M | MS28052C | Valve, Check, Pressure Gage Lines Bleeder and Filler [CUST: AS 99 CC] | A 4820 | CC | 14-OCT-2011 |
| M | MS51492A | Screw, Machine, Pan Head, Cross-Recessed, Carbon Steel, UNC-2A [CUST: AR 99 IS] | A 5305 | IS | 20-OCT-2011 |
| M | MIL-M-49231A NOT 2 | Modem, Cable, Driver, MD-1023()/G [CUST: CR] | A 5805 | CR | 25-OCT-2011 |
| M | MIL-M-49232A NOT 2 | Modem, Cable, Driver, MD-1024()/G [CUST: CR] | A 5805 | CR | 25-OCT-2011 |
| M | MIL-M-49233A NOT 2 | Modem, Cable Driver MD-1025()/G [CUST: CR] | A 5805 | CR | 25-OCT-2011 |
| M | MIL-M-49238A NOT 2 | Multiplexer, TD-1233()/TTC [CUST: CR] | A 5805 | CR | 25-OCT-2011 |
| M | MIL-R-55602A(2) NOT 2 | Restorer, Pulse Form TD-206B/G [CUST: CR] | A 5805 | CR | 18-OCT-2011 |
| M | MIL-C-55607A(3) NOT 3 | Converter, Telephone Signal CV-1548()/G [CUST: CR] | A 5805 | CR | 26-OCT-2011 |
| M | MIL-M-55650B(1) NOT 3 | Multiplexer TD-660()/G [CUST: CR] | A 5805 | CR | 26-OCT-2011 |
| M | MIL-R-49023 NOT 2 | Radio Set AN/GRC-103 (V) 1 [CUST: CR 99] | A 5820 | CR | 18-OCT-2011 |
| M | MIL-R-49237A NOT 2 | Restorer, Pulse Form, TD-1219()/G [CUST: CR] | A 5820 | CR | 25-OCT-2011 |
| M | MIL-R-55656(2) NOT 3 | Radio Set, AN/GRC-103() (V) (Basic) [CUST: CR] | A 5820 | CR | 26-OCT-2011 |
| M | MIL-P-55695(2) NOT 2 | Power Supply PP-4763()/GRC [CUST: CR] | A 5820 | CR | 26-OCT-2011 |
| M | MIL-S-55389(2) NOT 2 | Suppressor, Electrical Transient, MX-7778A/GRC [CUST: CR] | A 5915 | CR | 26-OCT-2011 |
| M | MIL-PRF-15160/6E | Fuses; Instrument, Power, and Telephone (Nonindicating), Style F06 [CUST: CR SH 85 CC] [REVIEW: 19 99 AS AT CG CR4 EC MC MI] | A 5920 | CC | 12-OCT-2011 |
| M | MIL-PRF-15160/30B | Fuses, Style F30 [CUST: CR SH 85 CC] [REVIEW: 99 MI] | A 5920 | CC | 12-OCT-2011 |
| M | MIL-PRF-15160/36B | Fuses, Style F36 [CUST: CR SH 85 CC] [REVIEW: 99] | A 5920 | CC | 12-OCT-2011 |
| M | MIL-PRF-15160/37B | Fuses, Style F37 [CUST: CR SH 85 CC] [REVIEW: 99] | A 5920 | CC | 12-OCT-2011 |
| M | MIL-PRF-15160/38B | Fuses, Style F38 [CUST: CR SH 85 CC] [REVIEW: 99] | A 5920 | CC | 12-OCT-2011 |
| M | MIL-PRF-15160/39B | Fuses, Style F39 [CUST: CR SH 85 CC] [REVIEW: 99] | A 5920 | CC | 12-OCT-2011 |
| M | MS24614L | Switch, Toggle, Positive Break, Lever Lock, Environmentally Sealed, Screw Terminal, Four Pole, .469 Mounting Bushing 25 Amperes [CUST: CR AS 85 CC] | A 5930 | CC | 05-OCT-2011 |
| N | MIL-DTL-32401 | Terminal Board Assembly, Two Stud [CUST: AS 85 GS] [REVIEW: 99] | A 5940 | GS4 | 27-OCT-2011 |
| M | MIL-R-5757J SUP 1 | Relays, Electromagnetic, General Specification for [CUST: CR EC 85 CC] [REVIEW: 99 AS AT AV CR4 MC MI OS] | A 5945 | CC | 11-OCT-2011 |
| M | MS25471F | Wire, Electrical, Silicone-Insulated, Copper, 600 Volt, 200 Degrees C, Polyester Jacket [CUST: AV AS 85 CC] | A 6145 | CC | 19-OCT-2011 |
| M | MS27110E | Wire, Electrical - Silicone Insulated, Copper, 600 Volt, 200 Degrees C, FEP Jacket [CUST: AV AS 85 CC] | A 6145 | CC | 19-OCT-2011 |
| M | MIL-DTL-8954C NOT 1 | Base and Accessories, Airport Marker Lights, General Specification for [CUST: AS 99 GS2] [REVIEW: IS] | A 6210 | GS2 | 20-OCT-2011 |
| M | MS26580B NOT 2 | Cover, Airport Marker Light Base, Blank [CUST: AS 99 GS2] [REVIEW: IS YD] | A 6210 | GS2 | 20-OCT-2011 |

CANCELED SECTION

ASSIST UPDATE

| LAST ACTION | | | DISTRIBUTION | FSC/AREA | MCA | PREP ACTY | DATE |
|-------------|------------------------|--|--------------|----------|-----|-----------|-------------|
| | DOCUMENT NUMBER | DOCUMENT TITLE | | | | | |
| M | MS24370B NOT 4 | Rim Contours-24 X 5.5, 22 X 5.5, 20 X 5.5 and 18 X 5.5, Type VII, Extra High Pressure, Landing Gear Wheel (No S/S Document) [CUST: AV AS 70] [REVIEW: GS MC] | A | 1630 | | 70 | 27-OCT-2011 |
| M | AND10583 REV B NOT 4 | Rim Contour-25.00-28, Type III, Low Pressure, Main Landing Gear Wheel (No S/S Document) [CUST: AV AS 70] [REVIEW: GS] | A | 1630 | | 70 | 27-OCT-2011 |
| M | ANSI-B94.2 | Reamers (No S/S Document) [CUST: AR SH 99 GS] [REVIEW: 84 CR4] | A | 3455 | | GS6 | 20-OCT-2011 |
| M | ANSI-B94.19 | Milling Cutters and End Mills (No S/S Document) [CUST: AR 99 GS] | A | 3455 | | GS6 | 20-OCT-2011 |
| M | API-STD-1529 | Aviation Fueling Hose and Hose Assemblies (S/S by EI-1529) [CUST: CR4 YD 99 CC] [REVIEW: 71 AS SH] | A | 4720 | | CC | 05-OCT-2011 |
| M | MS9012A NOT 1 | Ring-Retaining External, Beryllium Copper (S/S by MS16624) [CUST: AS] [REVIEW: IS MI] | A | 5340 | | AS | 20-OCT-2011 |
| M | MS9013B NOT 1 | Ring-Retaining, External, Steel (ASG) (S/S by MS16624) [CUST: AS] [REVIEW: AR IS MI] | A | 5340 | | AS | 20-OCT-2011 |
| M | MIL-G-12519(2) NOT 3 | Generator, Ringing, Hand GN-38-3 (No S/S Document) [CUST: CR] | A | 5805 | | CR | 20-OCT-2011 |
| M | MIL-M-49143 NOT 3 | Multiplexer, Time Division Digital TD-1069 ()/G (No S/S Document) [CUST: CR] | A | 5805 | | CR | 20-OCT-2011 |
| M | MIL-P-49115A(2) NOT 1 | Platoon Early Warning System AN/TRS-2() (No S/S Document) [CUST: CR] | A | 5895 | | CR | 20-OCT-2011 |
| M | A-A-59705A NOT 1 | Fuse Cartridge, Low-Voltage, Class RK5, Blown Fuse Indication, General Requirements for (No S/S Document) [CUST: EC CC] | A | 5920 | / | CC | 15-OCT-2011 |
| M | A-A-59705/1A NOT 1 | Fuse Cartridge, Dual-Element, Time-Delay, Class RK5 250 Volts (V), Blown Fuse Indication (No S/S Document) [CUST: EC CC] | A | 5920 | / | CC | 15-OCT-2011 |
| M | A-A-59705/2A NOT 1 | Fuse Cartridge, Dual-Element, Time-Delay, Class RK5 600 VOLTS (V), Blown Fuse Indication (No S/S Document) [CUST: EC CC] | A | 5920 | / | CC | 15-OCT-2011 |
| M | A-A-59705/3A NOT 1 | Fuse Cartridge, Time-Delay, Class RK5 600 Volts (V), Blown Fuse Indication (No S/S Document) [CUST: EC CC] | A | 5920 | / | CC | 15-OCT-2011 |
| M | MS24570A NOT 5 | Switch, Vehicular Ignition: Waterproof, Starter and Magneto, with Degasser Control (No S/S Document) [CUST: AT MC 85 CC] | A | 5930 | | CC | 03-OCT-2011 |
| M | MS25044B NOT 3 | Terminal Board, Two Stud (S/S by MIL-DTL-32401) [CUST: AS 85 GS] [REVIEW: 99] | A | 5940 | | GS4 | 27-OCT-2011 |
| M | MIL-R-55168B NOT 3 | Retransmission Cable Kit MK-456 ()/GRC (Units of) (No S/S Document) [CUST: CR GS] | A | 5995 | | GS4 | 17-OCT-2011 |
| M | EIA455 | Fiber Optic Fibers, Cables, Transducers, Sensors, Connecting and Terminating Devices, and Other Fiber Optic Components (S/S by TIA455) [CUST: CC] | A | 60GP | | CC | 12-OCT-2011 |
| M | EIA455.2 | Optic Devices, Fiber, Impact Test Measurements for (S/S by TIA455.2) [CUST: CR AS 85 CC] [REVIEW: 19 EC MC MI SH SM TE] | A | 60GP | | CC | 12-OCT-2011 |
| M | EIA455.3 | Optical Fibers, Optical Cable, and Other Passive Fiber Optic Components, Procedure to Measure Temperature Cycling Effects on (S/S by TIA455.3) [CUST: CR AS 85 CC] | A | 60GP | | CC | 12-OCT-2011 |
| M | EIA455.4 | Fiber Optic Connector/Component Temperature Life (S/S by TIA455.4) [CUST: CR AS 85 CC] [REVIEW: 13 19 EC MC SH TE] | A | 60GP | | CC | 12-OCT-2011 |
| M | EIA455.5 | Fiber Optic Components, Humidity Test Procedure for (S/S by TIA455.5) [CUST: CR AS 85 CC] | A | 60GP | | CC | 12-OCT-2011 |
| M | EIA455.6 | Cable Retention Test Procedure for Fiber Optic Cable Interconnecting Devices (S/S by TIA455.6) [CUST: CR AS 85 CC] | A | 60GP | | CC | 12-OCT-2011 |
| M | EIA455.18 | Optic Components and Assemblies, Fiber, Acceleration Testing of (S/S by TIA455.18) [CUST: CR AS 85 CC] [REVIEW: 19 EC MC SH TE] | A | 60GP | | CC | 12-OCT-2011 |
| M | EIA455.21 | Fiber Optic, Interconnecting Devices, Mating Durability of (S/S by TIA455.21) [CUST: CR AS 85 CC] [REVIEW: 13 19 EC MC SH TE] | A | 60GP | | CC | 12-OCT-2011 |
| M | EIA455.22 | Fiber Optic Components, Ambient Light Susceptibility of (S/S TIA455.22) [CUST: CR AS 85 CC] [REVIEW: 13 19 EC MC SH TE] | A | 60GP | | CC | 12-OCT-2011 |
| M | EIA455.23 | Fiber Optic Component Seals, Air Leakage of (S/S by TIA455.23) [CUST: CR AS 85 CC] [REVIEW: 19 EC MC SH TE] | A | 60GP | | CC | 12-OCT-2011 |
| M | MIL-STD-1564A(2) NOT 3 | Procedure for Calibration and Analysis of Trace Contaminants in Aviator's Breathing Oxygen by Infrared Spectroscopy (S/S by CGA-G4.3) [CUST: AS 68 GS] | A | 6830 | | 68 | 27-OCT-2011 |
| M | MIL-HDBK-881A NOT 1 | Work Breakdown Structures for Defense Materiel Items (S/S by MIL-STD-881) [CUST: MI SH 10 WB] [REVIEW: 11 16 19 70 71 84 AR AS AT AV CR MC OS SH] | A | MISC | | WB | 03-OCT-2011 |